

| AREA | |
|------------|--------|
| INSPECTED: | School |
| · | |

| INSPECTION LIST | | RATING | INSPECTOR'S COMMENTS |
|----------------------|---|------------------------|---|
| | | | |
| Safety | Wet, Slippery Floors | 12.,3 4 | .5. |
| | Obstructed Aisles or Exits | 123 4 | .5. |
| | Storage Too High | 123 4 | .5. |
| | Mechanical Problems | 123 | .5 |
| | Other | 123 4 | 5 |
| | | | |
| Sanitation | Walls, Ceilings, and Floors | 1234 | 5 1# Water leak in room 205left corner of room. |
| | Windows | 12.,3 | 5 |
| | Stairs | 123 4 | 5 |
| | Toilets, Showers, and Basins | 123 4 | 5 |
| | Storage Areas | 123 4 -2 | 5 |
| | Trash Removal | 12.,3 4 | 5 |
| | | | |
| Fire Safety | Fire Extinguishers | 123 4 4 | 5 |
| | Sprinkler System | 12.,3., 45- | 5 |
| | Fire Alarm System | 1234 | 5 #2 Main fire alarm out, 15 min fire checks being completed. |
| | Exit Signs | 123 4 | 5 |
| | Emergency Lighting | 123 4 | 5 |
| | Posted Evacuation Plans | 1234 | 5 3# Fire evacuation plans not on walls. (Put back on wall) |
| | | | |
| Hazardous | Proper Storage | 123 4 | 5 |
| Materials | Supervision | 123 | 5 |
| | Accountability | 123 4 | 5 |
| | | | |
| Vermin | Evidence of Vermin | 123 2 | 5 |
| Control | Other | 123 4 | 5 |
| | | | |
| Post Orders | Availability | 12.,3 | 5 |
| | Staff Review | 123 | 5 |
| | | | |
| Summary | v. 1# Water leak in room 205le | ft corner of room. | |
| | #2 Main fire alarm out. 15 min | fire checks being con | npleted. |
| | 3# Fire evacuation plans not of | on walls. (Put back on | wall) |
| | | | |
| | | | |
| | | | |
| | | | |
| Rating: Description: | | Description: | |
| | | | ate correction (Do not leave the area till resolved |
| 2. Unsatis | *************************************** | | ion within 48 hours |
| 3. Below S | | | n of Correction (Resolved within 10 days) |
| | | | y and continue improving) |
| | ls Standard | Continue at thi | |
| | | Jonande at III | |
| Comple | eted by: M.Craig | | Date: 7-19-13 |